VOLKSWAGEN P1026: ACTIVATION INTAKE MANIFOLD FLAP FOR AIR STREAM REGULATION SHORT CIRCUIT TO B+

OVERVIEW

Severity : High

DIY Difficulty Level : Advanced

Repair Cost : \$200-\$620

Can I Still Drive? : Yes (Short-term only)

What Does The Volkswagen P1026 Code Mean?

The ECM detected a voltage irregularity on the intake manifold flap.

What Are The Potential Causes Of The Volkswagen P1026 Code?

Check activation of intake manifold flap for air stream regulation

Reference Sources

Volkswagen P1026, DTCDECODE.

