

VOLKSWAGEN P1027: ACTIVATION INTAKE MANIFOLD FLAP FOR AIR STREAM REGULATION SHORT CIRCUIT TO GROUND

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$200-\$620
Can I Still Drive?	:	Yes (Short-term only)

What Does The Volkswagen P1027 Code Mean?

The ECM detected a voltage irregularity on the intake manifold flap.

What Are The Potential Causes Of The Volkswagen P1027 Code?

Check activation of intake manifold flap for air stream regulation

Reference Sources

[Volkswagen P1027](#), DTCDECODE.