

VOLKSWAGEN P1500: FUEL PUMP RELAY CIRCUIT ELECTRICAL MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Volkswagen P1500 Code Mean?

Engine running the ECM detected that the fuel pump relay signal was intermittent

What Are The Potential Causes Of The Volkswagen P1500 Code?

- Fuel delivery unit connector is loose or not attached
- Fuse 18 cause a short to the transfer fuel pump or the O2S
- Fuel pump has failed
- Fuel pump relay circuit is shorted to ground, B+ or is open
- Fuel Pump (FP) Relay not activated
- ECM has failed

Reference Sources

[Volkswagen P1500](#), DTCDECODE.