ACURA B1005: MICU LOST COMMUNICATION WITH RELAY CONTROL MODULE (RM MESSAGE)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	**$75-$200**
Can I Still Drive?	:	**Yes** (Short-term only)

What Does The Acura B1005 Code Mean?

This code indicates PCM or F-CAN loss of communication, B-CAN system loss of communication.

NOTE: If you are troubleshooting multiple DTC's, be sure to follow the instructions in B-CAN system diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1005 Code?

Below are some possible causes of this DTC:

- Faulty battery or charging system
- PCM or F-CAN poor connections or loose pins at connectors
- B-CAN system poor connections or loose pins at connectors
- Faulty relay control module

Reference Sources

Accessories & Equipment Multiplex Integrated Control System Service Manual for B1005 - 2004 Acura TSX, pages 40-41.

OBDCodeX

https://obdadvisor.com/codes/code/acura-b1005