

ACURA B1008: MICU LOST COMMUNICATION WITH GAUGE CONTROL MODULE (A/T MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1008 Code Mean?

Communication between the MICU and Gauge Control Module

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1008 Code?

- Faulty battery or charging system
- Loose or poor connections between the MICU and gauge control module
- "Open" in the communication circuit between the MICU and the gauge control module
- Faulty MICU
- Faulty gauge control module

Reference Sources

[Accessories & Equipment Multiplex Integrated Control System Service Manual for B1008](#) - 2004 Acura TSX, page 42.