

ACURA B1015: MICU LOST COMMUNICATION WITH DRIVER'S MPCS UNIT (DRLOCKSW MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1015 Code Mean?

Poor communication MICU and the Driver's MPCS unit. If DTCs [B1065](#), [B1082](#), [B1356](#), [B1358](#), and/or [B1905](#) are indicated with [B1013](#) and/or B1015. Perform the driver's MPCS unit input test

What Are The Potential Causes Of The Acura B1015 Code?

- Loose or poor connections between the MICU and the driver's MPCS unit
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground at driver's MPCS unit
- "Open" or "Short" to ground at driver's MICU unit
- Faulty power window switch
- Faulty power window relay
- Faulty power window motor

Reference Sources

[Acura B1015](#), DTCDECODE.