

ACURA B1050: COMMUNICATION BUS LINE ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes

What Does The Acura B1050 Code Mean?

Poor Bus line communication.

What Are The Potential Causes Of The Acura B1050 Code?

- Loose or poor connections at the MICU and B-CAN connected units
- Faulty relay control module

Reference Sources

[Accessories & Equipment Multiplex Integrated Control System Service Manual for B1050](#) - 2004
Acura TSX, pages 39-40.