

ACURA B1051: RELAY CONTROL MODULE INTERNAL (CPU) ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	Yes

What Does The Acura B1051 Code Mean?

Relay Control Module Internal Failure

What Are The Potential Causes Of The Acura B1051 Code?

Faulty relay control module, replace the under-hood fuse/relay box

Reference Sources

[Acura B1051](#), DTCDECODE.