

ACURA B1055: RELAY CONTROL MODULE LOST COMMUNICATION WITH MICU (MICU MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1055 Code Mean?

Poor communication between the Relay Control Module and the MICU.

If DTCs B1055, [B1056](#), [B1057](#), [B1157](#), [B1159](#), [B1180](#), [B1255](#), [B1955](#), [B2155](#), [B2156](#), and [B2161](#) are all indicated, perform the MICU input test.

What Are The Potential Causes Of The Acura B1055 Code?

- Loose or poor connections between the Relay Control Module and the MICU
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground at driver's MPCU unit
- "Open" or "Short" to ground at driver's MICU
- "Open" or "Short" to ground at driver's Relay Control Module
- Faulty Relay Control Module
- Faulty MICU

Reference Sources

[Acura B1055](#), DTCDECODE.