

## ACURA B1063: RELAY CONTROL MODULE LOST COMMUNICATION WITH COMBINATION SWITCH CONTROL UNIT (WIPSW MESSAGE)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Acura B1063 Code Mean?

Poor communication between Relat Control Module and the Combination Switch Control Unit (WIPSW Message).

### What Are The Potential Causes Of The Acura B1063 Code?

- Loose or poor connections between the Relay Control Unit and the Combination Control Unit.
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground at the Relay Control Unit
- "Open" or "Short" to ground at the Combination Control Unit.
- Faulty Relay Control Unit
- Faulty Combination Control Unit

### How Can You Fix The Acura B1063 Code?

- If DTCs [B1007](#), [B1062](#), B1063, [B1155](#), [B1156](#), [B1957](#), [B1958](#), and [B2969](#) all indicated, perform the combination switch control unit input test.

## Reference Sources

[Acura B1063](#), DTCDECODE.