

ACURA B1078: DAYTIME RUNNING LIGHTS SYSTEM ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The Acura B1078 Code Mean?

Daytime Running Lights Inoperable.

What Are The Potential Causes Of The Acura B1078 Code?

- Blown fuse No. 1 (10 A) and No. 2 (10 A) in the under-hood fuse/relay box
- Faulty bulbs
- Poor continuity between daytime running light 2P connector terminal No. 2 and under-hood fuse/relay box connector G (4P) terminals No. 1 and No. 2 respectively.
- Open in the BLK wire or poor ground (G201-right side, G301-left side)
- Faulty Relay Control Module

Reference Sources

[Acura B1078](#), DTCDECODE.