

## ACURA B1133: LEFT REAR POWER WINDOW MOTOR PULSE B ERROR

### OVERVIEW

|                      |   |                                |
|----------------------|---|--------------------------------|
| Severity             | : | <div><div>Medium</div></div>   |
| DIY Difficulty Level | : | <div><div>Advanced</div></div> |
| Repair Cost          | : | \$250-\$510                    |
| Can I Still Drive?   | : | <b>Yes</b> (Short-term only)   |

### What Does The Acura B1133 Code Mean?

This code indicates inoperative or intermittent operation of the left rear power window motor.

**NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

### What Are The Potential Causes Of The Acura B1133 Code?

Below are some possible causes of this DTC:

- Loose or poor connections between the window motor and switch
- "Open" between left rear power window switch and ground
- "Open" or "Short" between the window motor and switch
- Faulty left rear power window switch
- Faulty left rear power window motor

### Reference Sources

[Acura B1133](#), DTCDECODE.