

## ACURA B1148: LEFT REAR POWER WINDOW SWITCH INTERNAL ERROR

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div>Advanced</div>
Repair Cost	:	\$200-\$550
Can I Still Drive?	:	Yes

### What Does The Acura B1148 Code Mean?

Inoperative or intermittent operation of the left rear power window motor.

**NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

### What Are The Potential Causes Of The Acura B1148 Code?

- Loose or poor connections
- Faulty left rear power window switch

### Reference Sources

[Acura B1148](#), DTCDECODE.