

ACURA B1159: GAUGE CONTROL MODULE LOST COMMUNICATION WITH MICU (DOORSW MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1159 Code Mean?

Poor communication between the Gauge Control Module and the MICU.

If DTCs [B1055](#), [B1056](#), [B1057](#), [B1255](#), [B1955](#), [B2155](#), [B2156](#), and/or [B2161](#) are all indicated, perform the MICU input test.

If no additional codes are present, perform the Gauge Control Module input test.

What Are The Potential Causes Of The Acura B1159 Code?

- Loose or poor connections between the Gauge Control Module and the MICU
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground at the Gauge Control Module
- "Open" or "Short" to ground at the MICU
- Faulty Gauge Control Module
- Faulty MICU

Reference Sources

[Acura B1159](#), DTCDECODE.