

ACURA B1205: CLIMATE CONTROL UNIT LOST COMMUNICATION WITH GAUGE CONTROL MODULE (VSP/NE MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1205 Code Mean?

Poor communication between the Climate Control Unit and the Gauge Control Module.

What Are The Potential Causes Of The Acura B1205 Code?

- Loose wires or poor connections at the Climate Control Unit
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" Condition between the Climate Control Unit and the Gauge Control Module
- Poor Ground condition at the Climate Control Unit
- Faulty Climate Control Unit
- Faulty Gauge Control Module

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1205](#) - Pages 35-36.