

ACURA B1208: CLIMATE CONTROL UNIT LOST COMMUNICATION WITH KEYLESS ACCESS CONTROL UNIT (FOB ID MESSAGE)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1208 Code Mean?

Poor communication the climate control unit and keyless access control unit.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN system diagnosis test mode A.

What Are The Potential Causes Of The Acura B1208 Code?

- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- Perform the climate control self-diagnostic with the HDS or the climate control unit
- Perform the gauge control module input test
- Loose wires or poor connections on the B-CAN lines between the gauge control module circuit
- Faulty climate control unit
- Faulty gauge control module
- Faulty keyless access control unit

Reference Sources

[Acura B1208](#), DTCDECODE.