

ACURA B1214: SHORT IN THE REAR EVAPORATOR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1214 Code Mean?

This code indicates poor communication between the Rear Evaporator Temperature Sensor and the Climate Control Unit.

What Are The Potential Causes Of The Acura B1214 Code?

Below are some possible causes of this DTC:

- Perform the HVAC or climate control unit self-diagnostic function, with the HDS
- "Short" in the wires between the climate control unit and the rear evaporator temperature sensor
- Faulty Rear Evaporator Temperature Sensor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1214](#) - Pages 38-39.