

ACURA B1223: PROBLEM IN THE REAR BLOWER MOTOR CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$150
Can I Still Drive?	:	Yes

What Does The Acura B1223 Code Mean?

Rear Blower Motor inoperable or intermittent condition.

What Are The Potential Causes Of The Acura B1223 Code?

- Perform the HVAC self-diagnostic function with the HDS
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- Loose wires or poor connections on the rear blower motor circuit
- Faulty GRD Circuit
- Faulty Rear Blower Motor relay
- Faulty Rear Blower Motor

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1233](#) - Pages 42-49.