

ACURA B1226: SHORT IN THE IN-CAR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes

What Does The Acura B1226 Code Mean?

Poor communication between the In-car Temperature Sensor and the Climate Control Unit. ("Short") circuit.

What Are The Potential Causes Of The Acura B1226 Code?

- Perform the HVAC self-diagnostic function with the HDS
- "Short" in the wires between the Climate Control Unit and the in-car temperature sensor
- Faulty In-car Temperature Sensor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1226](#) - Pages 51-52.