

ACURA B1232: SHORT IN THE FRONT EVAPORATOR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

What Does The Acura B1232 Code Mean?

Poor communication between the Front Evaporator Temperature Sensor and the Climate Control Unit ("Short") condition.

What Are The Potential Causes Of The Acura B1232 Code?

- Perform the HVAC self-diagnostic function with the HDS
- "Short" in the wires between the Climate Control Unit and the Front Evaporator Temperature Sensor
- Faulty Front Evaporator Temperature Sensor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1232](#) - Pages 61-63.