

## ACURA B1233: OPEN IN THE DRIVER'S AIR MIX CONTROL MOTOR CIRCUIT

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes

### What Does The Acura B1233 Code Mean?

Poor communication between the Driver's Air Mix Control Motor and the Climate Control Unit ("Open") condition.

### What Are The Potential Causes Of The Acura B1233 Code?

- Perform the HVAC self-diagnostic function with the HDS
- "Open" in the wires between the Climate Control Unit and the Driver's Air Mix Control Motor
- Faulty Driver's Air Mix Control Motor
- Faulty Climate Control Unit

### Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1233](#) - Pages 63-64.