

ACURA B1235: PROBLEM IN THE DRIVER'S AIR MIX CONTROL LINKAGE, DOOR, OR MOTOR CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes

What Does The Acura B1235 Code Mean?

Poor communication between the Driver's Air Mix Control Motor and the Climate Control Unit. ("Open") condition and/or linkage problem.

What Are The Potential Causes Of The Acura B1235 Code?

- Perform the HVAC self-diagnostic function with the HDS
- Loose wires or poor connections on the Driver's Air Mix Control Motor circuit
- Driver's air mix control linkage or door
- "Open" in the wires between the Climate Control Unit and the Driver's Air Mix Control Motor
- Faulty Driver's Air Mix Control Motor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1235](#) - Pages 69-71.