

ACURA B1236: OPEN IN THE PASSENGER'S AIR MIX CONTROL MOTOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes

What Does The Acura B1236 Code Mean?

Poor communication between the Passenger's Air Mix Control Motor and the Climate Control Unit ("Open") condition.

What Are The Potential Causes Of The Acura B1236 Code?

- Perform the HVAC self-diagnostic function with the HDS
- Loose wires or poor connections on the Passenger's Air Mix Control Motor
- "Open" in the wires between the Climate Control Unit and the Passenger's Air Mix Control Motor
- Faulty Passenger's Air Mix Control Motor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1236](#) - Pages 71-72.