ACURA B1237: SHORT IN THE PASSENGER'S AIR MIX CONTROL MOTOR CIRCUIT OVERVIEW

Severity

DIY Difficulty Level

Repair Cost \$90-\$150

Can I Still Drive? Yes (Short-term only)

What Does The Acura B1237 Code Mean?

This code indicates poor communication between the Passenger's Air Mix Control Motor and the Climate Control Unit - ("Short") condition.

What Are The Potential Causes Of The Acura B1237 Code?

Below are some possible causes of this DTC:

- Perform the HVAC self-diagnostic function with the HDS
- "Short" in the wires between the Climate Control Unit and the Passenger's Air Mix Control Motor
- Faulty Passenger's Air Mix Control Motor
- Faulty Climate Control Unit

Reference Sources

2007-2009 Acura MDX HVAC Climate Control Service Manual for B1237 - Pages 72-77.

