

ACURA B1237: SHORT IN THE PASSENGER'S AIR MIX CONTROL MOTOR CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1237 Code Mean?

This code indicates poor communication between the Passenger's Air Mix Control Motor and the Climate Control Unit – ("Short") condition.

What Are The Potential Causes Of The Acura B1237 Code?

Below are some possible causes of this DTC:

- Perform the HVAC self-diagnostic function with the HDS
- "Short" in the wires between the Climate Control Unit and the Passenger's Air Mix Control Motor
- Faulty Passenger's Air Mix Control Motor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1237](#) - Pages 72-77.