

## ACURA B1241: PROBLEM IN THE FRONT BLOWER MOTOR CIRCUIT

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	<b>\$80-\$150</b>
Can I Still Drive?	:	<b>Yes</b>

### What Does The Acura B1241 Code Mean?

Poor communication between the Front Blower Motor and the Climate Control Unit ("Open" or "Short") condition.

NOTE: Perform the HVAC self-diagnostic function with the HDS.

### What Are The Potential Causes Of The Acura B1241 Code?

- Loose wires or poor connections on the front blower motor circuit
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" in the wire(s) between the Climate Control Unit and the Front Power Transistor
- "Short" in the wire(s) between the Climate Control Unit and the Front Blower Motor
- Faulty Front Power Transistor
- Faulty Front Blower Motor
- Faulty Climate Control Unit

### Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B1241](#) - Pages 84-90.