

ACURA B1255: COMBINATION SWITCH CONTROL UNIT LOST COMMUNICATION WITH MICU (MICU MESSAGE)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$350
Can I Still Drive?	:	Yes

What Does The Acura B1255 Code Mean?

Poor communication between the Combination Switch Control Unit and the MICU.

If DTCs B1055, B1157, B1806, B1955, and B2155 are indicated, perform the MICU input test.

If DTCs [B1055](#), [B1057](#), [B1806](#), [B1955](#), and [B2155](#) are indicated, perform the MICU input test.

If no other codes are present perform the Combination Switch Control Unit input test

What Are The Potential Causes Of The Acura B1255 Code?

- Loose or poor connections between the Combination Switch Control Unit and the MICU
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground at the Combination Control Unit
- "Open" or "Short" to ground at the MICU
- Faulty MICU
- Faulty Combination Control Unit

Reference Sources

[Accessories & Equipment Multiplex Integrated Control System Service Manual for B1255](#) - 2004

Acura TSX, page 45.