

ACURA B1279: HEADLIGHT SWITCH DIMMER POSITION CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$150-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1279 Code Mean?

This code indicates intermittent or inoperable dimmer switch operation.

What Are The Potential Causes Of The Acura B1279 Code?

Below are some possible causes of this DTC:

- Loose or poor connections
- "Open" or "Short" in the combination light switch terminals
- Faulty Combination Switch Control Unit, replace the wiper/washer switch
- Faulty Combination Light Switch

Reference Sources

[Acura B1279](#), DTCDECODE.