

ACURA B1358: POWER TAILGATE CONTROL UNIT LOST COMMUNICATION WITH DRIVER'S MPCS UNIT (ASLOCKSW MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1358 Code Mean?

Poor communication between the Power Tailgate Control Unit and the drivers MPCS Unit. If DTCs [B1013](#), [B1015](#), [B1065](#), [B1182](#), and [B1905](#) are also indicated, perform the driver's MPCS unit input test. If no other codes are present, perform the power tailgate control unit input test.

What Are The Potential Causes Of The Acura B1358 Code?

- Loose or poor connections between the Power Tailgate Control Unit and the MICU
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" between the Power Tailgate Control Unit and the MICU
- Faulty Power Tailgate Control Unit
- Faulty MICU

Reference Sources

[Acura B1358](#), DTCDECODE.