

ACURA B1750: COMMUNICATION BUS LINE ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes

What Does The Acura B1750 Code Mean?

Poor Bus line communication.

What Are The Potential Causes Of The Acura B1750 Code?

- Loose or poor connections at the MICU and B-CAN connected units
- Faulty HandsFreeLink control unit

Reference Sources

[Acura B1750](#), DTCDECODE.