

## ACURA B1776: MICROPHONE INPUT/OUTPUT SHORT TO GROUND/OPEN

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Acura B1776 Code Mean?

This code indicates that the Microphone Input/Output is short to ground/open.

**NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN system diagnosis test mode A.

### What Are The Potential Causes Of The Acura B1776 Code?

Below are some possible causes of this DTC:

- "Short" to ground/open circuit
- Faulty harness between the HandsFreeLinks control unit and the roof console
- Faulty harness between the HandsFreeLink control unit and the Navigation Unit
- Faulty HFL control unit
- HandsFreeLink control unit

### Reference Sources

[Acura B1776](#), DTCDECODE.