

ACURA B1785: INCORRECT CONFIGURATION (VEHINFO FRAME)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1785 Code Mean?

This code indicates incorrect configuration in VEHINFO Frame.

What Are The Potential Causes Of The Acura B1785 Code?

Below are some possible causes of this DTC:

- Poor connections or loose terminals at the HandsFreeLink control unit
- Faulty Gauge Control Module

Reference Sources

[Acura B1785](#), DTCDECODE.