

ACURA B1802: POWER SEAT CONTROL UNIT INTERNAL (EEPROM) ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$250-\$400
Can I Still Drive?	:	Yes

What Does The Acura B1802 Code Mean?

Power Seat Control Unit Internal (EEPROM) Failure.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1802 Code?

Faulty Power Seat Control Unit

Reference Sources

[Acura B1802](#), DTCDECODE.