

ACURA B1805: POWER SEAT CONTROL UNIT LOST COMMUNICATION WITH GAUGE CONTROL MODULE (VSP/NE MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1805 Code Mean?

Poor communication between the Power Seat Control Unit and the Gauge Control Module.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A. If DTCs [B1011](#), [B1060](#), [B1061](#), [B1205](#), [B1357](#), [B1359](#), [B1408](#), [B1805](#), [B1806](#), [B1906](#), and [B2160](#) are also indicated, Perform the gauge control module input test.

What Are The Potential Causes Of The Acura B1805 Code?

- Loose or poor connections between the Power Seat Control Unit and the Gauge Control Module
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open or "Short" Condition between the Power Seat Control Unit and the Gauge Control Module
- Faulty Power Seat Control Unit
- Faulty Gauge Control Module

How Can You Fix The Acura B1805 Code?

If no addition codes are present, replace the Power Seat Control Unit.

Reference Sources

[Acura B1805](#), DTCDECODE.