

ACURA B1827: POWER SEAT REAR UP-DOWN MOTOR PULSE ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes

What Does The Acura B1827 Code Mean?

Power Seat Rear Up-down Motor Pulse malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1827 Code?

- Loose or poor connections at the Power Seat Control Unit connectors
- "Open or "Short" to ground
- Faulty rear up-down position sensor, replace the rear up-down motor
- Faulty Power Seat Control Unit

Reference Sources

[Acura B1827](#), DTCDECODE.