

ACURA B1836: POWER SEAT POSITION SENSOR CIRCUIT SHORT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$80-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1836 Code Mean?

Short in Power Seat Position Sensor Circuit.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1836 Code?

- Loose or poor connections at the Power Seat Control unit connector
- "Short" to ground in the wire of the recline motor/lumbar support motor subharness.
- Faulty Motor/Position Sensor
- Faulty Power Seat Control Unit

Reference Sources

[Acura B1836](#), DTCDECODE.