

ACURA B1840: TILT MOTOR PULSE ERROR

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$500
Can I Still Drive?	:	Yes

What Does The Acura B1840 Code Mean?

Tilt Motor Pulse malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1840 Code?

- Check for loose or poor connections
- "Open" or "Short" to ground
- Faulty Tilt Motor/Position Sensor, replace the tilt motor assembly
- Faulty Power Tilt/Telescopic Control Unit

Reference Sources

[Acura B1840](#), DTCDECODE.