

ACURA B1905: IMMOBILIZER-KEYLESS CONTROL UNIT LOST COMMUNICATION WITH DRIVER'S MPCS UNIT (DRLOCKSW MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1905 Code Mean?

Poor communication between the Immobilizer-Keyless Control Unit and the Driver's MPCS unit.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

If DTCs [B1013](#), [B1065](#), [B1182](#), and/or [B1356](#) are also indicated, perform the driver's MPCS unit input test.

If no additional codes are present, perform the Immobilizer-Keyless Control Unit input test.

What Are The Potential Causes Of The Acura B1905 Code?

- Loose or poor connections between the Immobilizer-Keyless Control Unit and the Driver's MPCS unit
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" to ground
- Faulty Driver's MPCS unit
- Faulty Immobilizer-Keyless Control Unit

Reference Sources

[Acura B1905](#), DTCDECODE.