

## ACURA B1958: REAR MICU LOST COMMUNICATION WITH COMBINATION SWITCH CONTROL UNIT (WIPSW MESSAGE)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Acura B1958 Code Mean?

Poor communication between the rear MICU and the Combination Switch Control Unit. (Wiper Malfunction)

**NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

If DTCs [B1007](#), [B1062](#), [B1063](#), B1155, [B1156](#), [B1957](#), [B1958](#), and/or [B2969](#) are indicated, perform the Combination Switch Control Unit input test.

If no codes are present, perform the rear MICU input test

### What Are The Potential Causes Of The Acura B1958 Code?

- Loose or poor connections between the rear MICU and the Combination Switch Control Unit.
- Blown fuse in the main under-hood fuse box
- Blown fuse in the under-dash fuse/relay box
- "Open" or "Short" Condition between the rear MICU and the Combination Switch Control Unit.
- Faulty Combination Switch Control Unit
- Faulty Rear MICU, replace the rear fuse/relay box.

## Reference Sources

[Acura B1958](#), DTCDECODE.