

ACURA B2150: COMMUNICATION BUS LINE ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$90-\$150
Can I Still Drive?	:	Yes

What Does The Acura B2150 Code Mean?

Poor Bus line communication.

What Are The Potential Causes Of The Acura B2150 Code?

- Faulty Multiplex Integrated Control Unit (MICU)
- Multiplex Integrated Control Unit (MICU) harness is open or shorted
- Multiplex Integrated Control Unit (MICU) circuit poor electrical connection

Reference Sources

[Acura B2150](#), DTCDECODE.