

ACURA B2155: DRIVER'S MPCS UNIT LOST COMMUNICATION WITH MICU (MICU MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2155 Code Mean?

This code indicates poor communication between the Driver's MPCS Unit and the MICU. (MICU malfunction).

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2155 Code?

Below are some possible causes of this DTC:

- Loose or poor connections between the driver's MPCS unit and the MICU
- "Open" or "Short" to ground
- Faulty MICU, replace the under-dash fuse/relay box
- Faulty Driver's MPCS unit

Reference Sources

[Acura B2155](#), DTCDECODE.