

## ACURA B2179: DRIVER'S DOOR KEY CYLINDER SWITCH LOCK/UNLOCK SIGNAL ERROR

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	Yes

### What Does The Acura B2179 Code Mean?

Driver's Door Key Cylinder Switch malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

### What Are The Potential Causes Of The Acura B2179 Code?

- Check for loose or poor connections
- "Open" or "Short" condition between the Driver's Door Key Cylinder Switch and the Driver's MPCS unit
- Faulty door lock switch bulb
- Faulty Driver's Door Key Cylinder Switch; replace the driver's door lock actuator assembly
- Faulty Driver's MPCS unit

### Reference Sources

[Acura B2179](#), DTCDECODE.