

ACURA B2185: RIGHT POWER MIRROR VERTICAL SENSOR SIGNAL ERROR

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$400
Can I Still Drive?	:	Yes

What Does The Acura B2185 Code Mean?

Right Power Mirror malfunction. (Vertical)

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2185 Code?

- Check for loose or poor connections
- "Open" or "Short" condition between the Right Power Mirror and the Front Passenger's MPCS unit
- Faulty Front Passenger's MPCS unit
- Faulty Right Power Mirror

Reference Sources

[Acura B2185](#), DTCDECODE.