## ACURA B2187: COMMUNICATION LINE (UART LINE) DRIVER'S MPCS UNIT CANNOT SEND UART MESSAGES.

**OVERVIEW** 

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$200-\$450

**Can I Still Drive?** : Yes (Short-term only)

## What Does The Acura B2187 Code Mean?

This code indicates Communication Line error.

**NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A. Perform Front Passenger's MPCS unit input test.

## What Are The Potential Causes Of The Acura B2187 Code?

Below are some potential causes of this DTC:

- "Short" to ground
- Faulty Moonroof Control Unit/Motor
- Faulty Driver's MPCS unit

## **Reference Sources**

Acura B2187, DTCDECODE.

