

ACURA B2187: COMMUNICATION LINE (UART LINE) DRIVER'S MPCS UNIT CANNOT SEND UART MESSAGES.

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$450
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2187 Code Mean?

This code indicates Communication Line error.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A. Perform Front Passenger's MPCS unit input test.

What Are The Potential Causes Of The Acura B2187 Code?

Below are some potential causes of this DTC:

- "Short" to ground
- Faulty Moonroof Control Unit/Motor
- Faulty Driver's MPCS unit

Reference Sources

[Acura B2187](#), DTCDECODE.