

ACURA B2188: COMMUNICATION LINE (UART LINE) DRIVER'S MPCS UNIT CANNOT RECEIVE UART MESSAGES FROM FRONT PASSENGER'S MPCS UNIT.

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$500
Can I Still Drive?	:	Yes

What Does The Acura B2188 Code Mean?

Communication Line (Open circuit)

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2188 Code?

- "Open" circuit
- Faulty Front Passenger's MPCS unit
- Faulty Driver's MPCS unit

Reference Sources

[Acura B2188](#), DTCDECODE.