

ACURA B2205: F-CAN COMMUNICATION LINE ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$80-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2205 Code Mean?

This code indicates poor communication between AcuraLink control unit (XM receiver) and the Gauge Control Module.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2205 Code?

Below are some potential causes of this DTC:

- Check the vehicle battery condition
- Poor connections or loose terminals at the AcuraLink control unit (XM receiver)
- "Open" circuit between AcuraLink control unit (XM receiver) and the Gauge Control Module
- AcuraLink control unit needs to be updated
- Faulty AcuraLink control unit

Reference Sources

[Acura B2205](#), DTCDECODE.