

ACURA B2206: SRS UNIT LOST COMMUNICATION WITH ACURALINK CONTROL UNIT (XM RECEIVER)

OVERVIEW

Severity	:	Medium	
DIY Difficulty Level	:	Intermediate	
Repair Cost	:	\$75-\$200	
Can I Still Drive?	:	Yes	

What Does The Acura B2206 Code Mean?

Poor communication between the SRS unit and acuraLink control unit.

Check for DTCs with the HDS and DTC log data in the navigation system diagnostic mode.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN system diagnosis test mode A.

What Are The Potential Causes Of The Acura B2206 Code?

- Poor connections or loose terminals at the AcuraLink control unit (XM receiver)
- AcuraLink control unit needs to be updated with the latest software
- “Open” circuit between the AcuraLink control unit (XM receiver) and the SRS unit
- Faulty acuraLink control unit

Reference Sources

[Acura B2206](#), DTCDECODE.