

ACURA B2207: NAVIGATION UNIT LOST COMMUNICATION WITH ACURALINK CONTROL UNIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B2207 Code Mean?

Poor communication between AcuraLink control unit (XM receiver) and the navigation unit.

What Are The Potential Causes Of The Acura B2207 Code?

- Check the vehicle battery condition
- "Open" circuit in the wire(s) between AcuraLink control unit (XM receiver) and the navigation unit
- "Short" to body ground in the wire(s) between the AcuraLink control unit (XM receiver) and the navigation unit
- Update the AcuraLink control unit with the latest software
- Faulty AcuraLink control unit (XM receiver)
- Faulty Navigation Unit

Reference Sources

[Acura B2207](#), DTCDECODE.