

What Does The Acura B2240 Code Mean?

XM Antenna malfunction.

What Are The Potential Causes Of The Acura B2240 Code?

- Check the vehicle battery condition
- Poor connections or loose terminals at the AcuraLink control unit (XM receiver) and the XM antenna
- Update the AcuraLink Control unit with the latest software
- Faulty AcuraLink Control unit
- Faulty antenna lead between the AcuraLink Control unit (XM receiver) and the XM antenna.
- Faulty XM antenna

Reference Sources

Acura B2240, DTCDECODE.

